



## *bj's* CLARITY™ Devitrification Solution

- Clean glass as usual
- Do not stir or shake bottle before application
- Using a foam brush or sprayer, lightly coat surface & sides of the top piece of glass only
- Do not allow the coating to migrate between or underneath the glass
- Allow to dry completely before moving to the kiln
- **Only use water to remove the coating**
- Wash brushes with clear water to clean
- Do not ingest and avoid contact with eyes
- Caution should always be used when applying any solution.
- Working temperatures around 1350F—1500F

*bj's* Clarity contains Borax. SDS sheet available on request 4-2021

GlasTile Inc/SilkeMat, 411 N Cedar St, Unit B, Greensboro NC 27401, USA 336-580-7063  
[sales@SilkeMat.com](mailto:sales@SilkeMat.com)      [www.SilkeMat.com](http://www.SilkeMat.com)

April 1, 2020